

NIOSH-00180403

Physiology of RADIATION and the work environment

FILE COPY

U.S. DEPARTMENT OF
health,
education, and
welfare

Public Health Service
Center for Disease Control
National Institute for
Occupational Safety and Health

ULTRAVIOLET RADIATION AND THE WORK ENVIRONMENT

Ultraviolet radiation is an invisible radiant energy that is produced by natural and artificial sources and accompanies much visible light. It makes fluorescent lamps light, instrument panel dials glow, and special effects appear in visual presentation. It is used also in chemical synthesis and analysis, product inspection, crime detection, medical diagnosis and treatment, photoengraving, photocopying, photo-electric scanning, and electrostatic processes.

The sun is the major natural source of ultraviolet radiation. Many artificial sources are found on the industrial scene, such as germicidal lamps, carbon arcs, welding and cutting torches, furnaces, and laboratory test and analysis equipment.

How Ultraviolet Radiation Can Harm You

Ultraviolet radiation can be injurious to the skin and particularly to the eyes. We are all familiar with skin damage as sunburn, which is caused by ultraviolet radiation that is part of the sun's light. How bad the sunburn is depends on the length of exposure and the intensity of the radiation, as well as on the individual's sensitivity. Continued exposure to ultraviolet radiation speeds skin aging and can even cause skin cancer, a condition most common among people who must work in the sun a lot, such as farmers, seamen, and power line workers.

Exposure of the eyes to ultraviolet radiation is particularly dangerous because the radiation cannot be seen or, at first, felt. Consequently, an individual being exposed is not always aware that his eyes are being affected. The invisible radiation may later produce discomfort due to its absorption by the outer layer of the eye. Conjunctivitis, the resulting condition (often called "ground glass eyeball" or "welder's flash"), usu-

ally occurs four to eight hours after exposure. It is extremely painful and, although usually temporary, can cause permanent injury to the eyes.

Controlling Exposure

Ultraviolet radiation is so readily absorbed by the human skin and eye that the exposure often is severe and becomes so painful that the worker quickly learns to protect himself thereafter. Prolonged exposure of the unprotected skin and eyes to ultraviolet radiation should always be avoided and persons with fair skin, especially, should avoid even occasional exposure. Barrier creams and lotions give some protection for brief exposures; however, protective clothing, gloves, and face shields are advised for all exposures, whether brief, intermittent, or prolonged. Enclosures or shields that are nontransparent to the radiation also can be used to control the exposure to radiation.

Approved goggles, properly fitted with appropriate lenses, are essential for all welding, cutting, and open-arc operations. Side and back screens should be used for these operations to protect nearby workmen. Remember that bright shiny surfaces can reflect harmful ultraviolet light from an open arc and should be masked or removed from the work areas.

Providing Ventilation

Ventilation is not needed to protect the worker's skin or eyes from radiation, but to remove toxic gases that may be created by the interaction of ultraviolet radiation with air and atmospheric contaminants. This interaction can produce hazardous concentrations of ozone, oxides of nitrogen, and other toxic gases. These toxic gases can be produced by the interaction of solvent vapors and ultraviolet radiation (or, for that matter, by contact of the gases with arcs or hot metal surfaces). For these reasons it is essential that workplaces where ultraviolet radiation is present be well ventilated, bearing in mind that photochem-

ical reactions can take place at some distance from both the ultraviolet source and the work operations where the solvent fumes originate.

Management's Responsibility

The plant doctor and work supervisor can help prevent damage from ultraviolet radiation by informing the workers of its potential hazards. Warning signs should be placed to alert workers in areas where there are open arcs and all safety measures should be rigidly enforced.

Workers who have been overexposed to ultraviolet radiation should be removed from the hazard immediately. The degree of injury and its cause should then be determined and measures to prevent a recurrence should be planned and put into effect.

Worker's Responsibility

Each worker should be aware of possible ultraviolet radiation in his work area and should follow these general rules and others issued by management to protect him on the job.

1. Stay away from all unnecessary exposure to ultraviolet radiation. Remove shiny metal objects from the work area.
2. Use all required protective equipment and clothing. Workers around high-powered germicidal lamps, welders, and workers using or working near lasers and plasma torches should wear appropriate eye protection.
3. If ventilation is necessary, check the system for adequate performance before starting work.
4. Report all ill effects and skin and eye disorders to the plant nurse or health unit.

**U.S. DEPARTMENT OF
HEALTH, EDUCATION, AND WELFARE**
Public Health Service
Center for Disease Control
National Institute for Occupational
Safety and Health

1973

74-121